TEAL™
A RED CAT COMPANY

Release Notes

Date: April 12, 2023

Version: 1.5.1

Aircraft: Golden Eagle and Teal 2 - 1.5.1.1043

Software: Teal QGC - 1.5.1.279

Summary: The 1.5.1 release for the Golden Eagle MK1 and Teal 2 contains:

- Fixes for issues related to metadata in still images and videos.

Field of View (FoV) information now in the metadata of the captured footage.

- Radio RSSI communication fix.

Software fix for handling different responses from Microhard radios.

- Added camera profiles for the Hadron 640 in TealQGC.

Users can now create automated survey missions with the proper camera settings and overlap.

- Improved GPS performance.

Improved performance by reducing interference.

Errata:

- Occasionally, the camera will allow the user to start recording video, but cannot be stopped. *Reference GE-792*

- The drone will not disarm after landing, and requires the user to use the emergency stop button. *Reference GE-791*

- Video may have a jello-like effect in video recordings and in the video stream. Reference GE-764 Drone will establish connection to the GCS, drop the link for a split second, and then will reconnect. *Reference GE-844*

- Drone's descent rate is really slow when landing at an elevation lower than the take off point. *Reference GE-755*

- Drone will reboot once on bootup. *Reference GE-621*

Update Instructions: Make sure to update your Golden Eagle or Teal 2 with the latest software to take advantage of these important fixes. For update instructions, please visit https://tealdrones.com/support/update-instructions/.

Field Service Bulletins: FSB-00002 (03/30/2023) for 1.5.0 is applicable to 1.5.1. Please visit https://tealdrones.com/support/field-service-bulletins, to access Field Service Bulletins.

Support: For further information, please contact Teal Drones Technical Support at (385) 281-8415 or support@tealdrones.com.

PROPRIETARY
2023 Teal Drones, Inc.