HOW TO PERFORM A COMPASS CALIBRATION

The Golden Eagle will need to be recalibrated when it has changed geographical locations (such as East Coast to West Coast). Please follow the instructions to calibrate the compass before its first flight.

You may follow along with our instructional video, ***Calibrating Drone Sensors: Teal Golden Eagle Drone*** on our website at: https://tealdrones.com/support/video/

INSTRUCTIONS

Connect the drone and the TAC.

1 - Touch the MENU icon.

2 - Select VEHICLE SETUP.

3 - Select SENSORS.

4 - Select COMPASS.

Be ready to pick up and rotate the drone.

5 - Click OK in the top right of the screen to begin.



PROPRIETARY
2022 TEAL DRONES, INC.

A tone from the Golden Eagle will alert you to begin. Hold the drone as instructed on the TAC screen until you hear a second tone and the orientation is marked completed.

Continue until all six (6) orientations are completed.



Select REBOOT VEHICLE when finished.



Reestablish the connection between the TAC and the drone.

For any questions or issues, please contact Teal Drones Technical Support at:
(385) 281-8415
SUPPORT@TEALDRONES.COM